

# Manhole Inspection Summary

# Manhole # S45E\_\_063MH

Printed On: 6/24/2010

Page 1 of 3

**Inspection**  Is Incomplete Rating: **3) Fair**

Record Plat: **45E** Node: **063** Status: **Found**

Insp Date: **7/23/08 10:16 AM**

Incomplete Comments

Crew: **jf,ct,sl**  
Inspector: **Provine, D**  
Firm: **JV**

**Location** Address: **Chapel**

Cross Street: **Lombard**

**Manhole** Type: **Terminal** Location: **Alley**

Ground Conditions: **Dry**

Prev. Rehab Weather: **Dry**

Subject To Ponding: **None**

Comments **Complete**

**Cover** Shape: **Circular** Diameter: **24** (in.) Length: (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties:  Bolted  Vented  Water Tight  Water Tight Insert

**Frame** Offset: **3** (in.) Condition:  Sound  Cracked  **Leaks**

**Chimney / Frame Adjustment**  Exists Material: **Brick**  Parged Height: **12** (in.)

Condition:  Sound  Cracked  Root Intrusion  **Loose Brick**  Deteriorated

Infiltration:  None  **Joint**  Cracks  **Mortar**  Roots  Wall

**Corbel** Material: **Brick**  Parged Type: **Concentric/Eccentric**

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  **Wall**

**Barrel** Material: **Brick**  Parged

Shape: **Circular** Diameter: **42** (in.) Length: (in.)

Condition:  Sound  Cracked  Root Intrusion  Loose Brick  Deteriorated

Infiltration:  None  Joint  Cracks  Mortar  Roots  **Wall**

**Bench**  Exists Material:  Parged

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  Debris

**Channel** Material: **Brick**  Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition:  Sound  Cracked  Root Intrusion  Deteriorated  Leaks  **Debris**

**Steps** Count: **4** Missing: **0**  Corroded

**Surcharge**  Evidence Of Surcharge Depth: (ft.)  Active Surcharge Present

Location View



Top View



Defect 1



Infiltration

Defect 2



Frame Leaks

# Manhole Inspection Summary

Manhole # S45E\_\_063MH

Printed On: 6/24/2010

Page 3 of 3

8 in. Circular Gravity Sewer  
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **8.4** (in.) Rod and Bar (Angled)

Pipe Material: **Clay**  Pipe Lined

Invert Depth: **9.25** (ft.) Flow Characteristics: **None**

Deposits:  None  Mud  Sludge  Debris  Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Sound**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection